

Volkswagen Passat

Broj šasijske: 1VWBN7A35CCXXXXXX

2014



Krađa



Korištenje



Brojač kilometara



**Financijski i pravni
status**



Oštećenje



+31

Izvori podataka





Provjerili smo 900+ izvora podataka u **35 država**

Fotografije

2017-04

8 fotografija





Korištenje

Je li vozilo korišteno kao taksi, vozilo za najam ili za neke druge usluge? Napomena: Takva vozila mogu biti u lošijem stanju nego obično!



Vozilo je korišteno kao vozilo za najam!

Evo što smo provjerili



Najam

⚠ Podatak je pronađen

Vozilo za najam



Taksi

✓ Podaci nisu pronađeni

Nema dokaza o korištenju
kao taksi



Transport

✓ Podaci nisu pronađeni

Nema dokaza o korištenju
kao transportnog vozila



Policijsko

✓ Podaci nisu pronađeni

Nema dokaza o korištenju vozila kao policijskog automobila



Invaliditet

✓ Podaci nisu pronađeni

Nema dokaza o korištenju vozila kao vozila za osobe s invaliditetom



Vozilo autoškole

✓ Podaci nisu pronađeni

Nema dokaza o korištenju vozila za školski prijevoz

Krađa

Je li vozilo trenutno označeno kao ukradeno? Je li bilo ukradeno u prošlosti? Je li pronađeno?



Vozilo je možda ukradeno!

Evo što smo provjerili:



Trenutačno se traži kao ukradeno

⚠ Podatak je pronađen

Datum nepoznat Litva



Ukradeno je u prošlosti

✓ Podaci nisu pronađeni

Trenutačni je status nepoznat



Ukradeno je u prošlosti

✓ Podaci nisu pronađeni

Vozilo je pronađeno

Provjera policijske baze podataka ukradenih vozila **izvršena je u sljedećim državama:**



Litva

⚠ Podatak je pronađen



Češka



Mađarska



Italija



Norveška

Brojač kilometara

Ima li znakova vraćene kilometraže ili neusklađenosti?



Ovo vozilo možda ima lažnu kilometražu!



Posljednja poznata kilometraža: 145.000 km




Prosječna kilometraža sličnih modela: 104.200 km



Pronađeno je 5 zapisa o kilometraži

 Vraćena kilometraža



Zapisi brojača kilometara

2014-01 **102.000 km**

2015-01 **129.000 km**

2016-02 **155.000 km**

2017-12 **136.000 km**

2018-09 **145.000 km**

 **Vraćanje brojača kilometara**

Financijski i pravni status

Je li vozilo prošlo tehničke preglede? Postoje li ograničena vlasnička prava ili aktivni krediti za vozilo?



Tehnički je pregled valjan

Pravni status



Tehnički pregled

Prošlo 2017-02



Litva

Prošlo je tehnički pregled



Otpad

✓ Podaci nisu pronađeni

Nema podataka da je vozilo označeno kao otpad



Izvezeno

✓ Podaci nisu pronađeni

Nisu pronađeni podaci o izvozu



Uvezeno

✓ Podaci nisu pronađeni

Nisu pronađeni podaci o uvozu

Financijska ograničenja



Leasing

✓ Podaci nisu pronađeni

Nema dostupnih podataka o aktivnim kreditima ili finansijskim ugovorima.



Operativni leasing

✓ Podaci nisu pronađeni

Nema podataka o operativnom leasingu na vozilo



Prodaja vozila u ime finansijske kuće

✓ Podaci nisu pronađeni

Nema podataka o prodaji vozila u ime finansijske kuće

Oštećenje

Je li ovo vozilo bilo oštećeno u prošlosti? Kolika je vrijednost oštećenja?



Ovo je vozilo bilo oštećeno 3 puta!



Ovo je vozilo bilo ozbiljno oštećeno!



Ozbiljna oštećenja mogu uzrokovati strukturalne probleme koja mogu učiniti vozilo nesigurnim za vožnju!

Zapisi o oštećenjima



Prednji desni dio / Branik



Ozbiljno oštećenje

 2018-03

Procijenjeni trošak popravka

17.000 €

Mogući uzrok oštećenja

Nepoznato



Eksterijer / Krov

Ozbiljno oštećenje

 2014-02

Procijenjeni trošak popravka

10.000 €

Mogući uzrok oštećenja

Nepoznato



Stražnji dio / Poklopac prtljažnika

Oštećenje

 2014-02

Procijenjeni trošak popravka

1.000 €

Mogući uzrok oštećenja

Nepoznato

Specifikacije & oprema

Koje su specifikacije i oprema zabilježeni za ovo vozilo?



Provjerite odgovaraju li specifikacije i oprema na ovom vozilu podacima koje vam je dao prodavatelj.

Identifikacija i tehničke specifikacije



Proizvođač
Volkswagen



Model
Passat



Vrsta karoserije
Limuzina



Godina proizvodnje
2014



Zapremnina
pogonskog sklopa
2 l



Snaga pogonskog
sklopa
103 kW (138 KS)



Vrsta prijenosa
Automatski



Lokacija tvornice
Njemačka

Oprema

E0A

Special editions

No special edition

0DI

Vehicle class differentiation units/platform components

Vehicle class differentiation -360-

1D0

Trailer hitch

Without trailer hitch

1E1

Activated carbon canister

Activated carbon canister

6XU

Exterior mirrors

automatically dimming, electrically adjustable, separately heated

5SL

Left exterior mirror

aspherical

1X0

Drive layout

Front wheel drive

A8B

Equipment levels

Basic equipment

J0L

Batteries

Battery 340 A (70 Ah)

4M3

1PA

Lockable wheel bolts

Standard wheel bolts

7MG

Emissions standard

Emission standard EU5

4UE

Airbag

Air bag for driver and front seat passenger

8ZH

Antennas

Antenna for AM/FM reception, "diversity"

EA0

Follow-on warranty

Without subsequent warranty

5RQ

Right exterior mirror

convex

9WL

"Multimedia", video/DVD/notebook connection

Multimedia socket for external audio source

1KW

Brake type in rear

Disc brakes, rear

1ZM

Brake type, front

Disc brakes, front (Geomet D)

NY0

Beverage holders

Cup holder

B0A

Component part sets with country-specific design requirements

Component parts set without country-specific design requirement

1AT

Brake systems

Electronic stabilization program (ESP)

9Z0

Operating voltage

Operating voltage 12V

7QA

CD ROM/DVD/SD card

Without CD/DVD for navigation

2H0

Charism

Without “drive select”

C26

General operating permit, alterations

Operating permit, alteration

3FA

Roof insert/convertible top

Without roof insert (standard roof)

G07

Suspension system in front

Front shock absorption

2G1

Insert for the filling up of unleaded fuel/fuel type

Insert for the filling up of unleaded fuel

7AL

Theft protection system

Battery/alternator capacity

Standard battery/alternator capacity

1S1

Tool kit and jack

Tool kit and jack

0XR

Owner's manuals

Information kit in Lithuanian

9T0

Heated washer nozzles

Without heated washer nozzles

7A0

CD changer/CD player

Without CD changer/CD player

QJ1

Chrome package

Chrome work package

3S0

Roof rails/roof load rack

Without roof rails/roof load rack

1JA

Suspension system in rear

Rear shock absorption, basic design 1

3X0

Ski bag

Without load-through provision

0EM

Installation differentiation for vehicle components

Installation differentiation for transmission MQ 200 vehicle components

7TM

Inserts

Anti-theft alarm system, passenger compartment control, backup horn and towing protection

7M0

Scuff plates

Plastic scuff plates in door apertures

UF0

Electric interface for external use

Without electric interface

6A0

Fire extinguishers

Without fire extinguisher

8K3

Headlight control

Separate daytime running lights with low beam assistant and “Coming Home” feature

7G0

Vehicle tracing system

Without preparation for VTS (vehicle tracking system)

8GG

Alternators

Alternator 110 A

0YC

Weight category rear axle

Weight range 3 installation control only, no requirement forecast

TU0

Base engine

4-cylinder gasoline engine 1.4 L unit 03C.K

8T0

Cruise control system

Without cruise control system (CCS)

Decorative inserts

7X0

Park distance control

Without park distance control

0FG

Manufacturing sequence differentiation

Mosel manufacturing sequence

VF0

Pedal cluster

Standard pedal cluster

UH2

Parking brake

Parking brake

F0A

Vehicle specifications

No special purpose vehicle, standard equipment

0G4

Transmission types/gearshift mechanisms

Cable gearshift

L01

Weight category front axle

Suspension range 01 installation control only, no requirement forecast

6M0

Tie down straps/net/pocket

Without tie down straps/net/pocket

VC0

Garage door opener

W/o remote-controlled garage door opener

G0K

Transmission specifications

6-speed manual transmission

3P1

Brackets

Bracket for first aid kit and warning triangle

KH6

Heating and air conditioning system

Electronically controlled air conditioning system

FC0

Customized installation

Without customized installation

U5A

Instrument clusters

Instrument insert, km/h speedometer

K8B

Body style

Notchback

6SE

Luggage compartment floor covering

Flat needle-punched trunk floor covering

QA0

Child seats

Without child seat

QR0

Compass/road sign display

Without compass/traffic sign display/traffic signs recognition

3Q6

Rear head restraints

Three rear headrests

6Y9

Cruise control system and speed limiter

W/o cruise control speed limit system

3NU

Rear seats

Rear seat bench unsplit, backrest split folding with center armrest

8ID

Headlamps

Halogen twin headlights

6T0

Interior light in footwell

Without interior light in footwell

4L6

Breakaway interior rearview mirror

Breakaway interior rear view mirror, automatically dimming

QK0

Camera/distance sensor

Without camera without distance sensor (driver assistance system)

4W0

Cassette and CD storage unit

Without cassette and CD storage unit

0Y3

Climatic zones

Cold zones

4D0

Seat ventilation/massage seat

Without seat ventilation/massage seat

5ZJ

Head restraints

Front headrests

1Z0

Fuel quantity for initial filling

Initial standard fuel filling

5C0

Body measures

Without special body measures

6P1

Rear license plate carrier

License plate bracket rear (ECE)

5K7

Paint preservative/transit coating

Transport protection film (minimum protection) with additional transport protection measures

FE0

Country codes

Without country code (no DVD player in vehicle)

8S7

Reading light

Two reading lights front

3H0

Backrest release

Without backrest release for front seats

2P1

Loading edge protection

Plastic trunk sill protection

1MR

Steering wheels

Leather steering wheel

8RM

Speaker installation

8 speakers (passive)

1A2

Fuel systems

Fuel system for SI engine with direct injection (FSI)

6KJ

Radiator grille

Radiator grille with chrome-plated strip

6W1

Front license plate carrier

License plate bracket front (large)

3GA

Rear luggage/load compartment floor

Without cargo area

L0L

Steering system arrangement

Left-hand drive vehicle

1N3

Steering

Speed-related variable steering assist (Servotronic)

8G0

Light control systems

Without light assistant

7P0

Lumbar support

Without lumbar support in seat backrests

AV1

Driving on the left/on the right

Driving on the right

8Q1

Headlight range control

Headlight-range adjustment

6E3

Center armrest

Front center armrest

3I5

Center console

Center console

8Z5

Engine cooling system

Not hot country

4SG

Left vanity mirror

**Left vanity mirror illuminated
extractable sun visor**

7Q0

Navigation device

Without navigation device

8WA

Front fog lamp/additional headlamp

Without front fog light

CZ0

Wheels

**Steel wheels 6.5J x 16 with optimized
weight**

9JA

Smoker's/non-smoker's package

Non-smoking package

NS0

Umbrella

Without umbrella(s)

V0A

Tire suppliers

Tires w/o specification of tire brand

9Q5

Multi-function display/trip computer

Multi-function display with control

EM0

Driver alert system

Without Rest Assist

D4X

Engine specifications

**4-cyl. gasoline engine 1.4 l/90 kW TSI
Base engine is TU0/TL1/TL8/T9B**

4TL

Right vanity mirror

**Vanity mirror, right, illuminated
extractable sun visor**

8TC

Rear fog lamp

Rear fog light for driving on the right

1NH

Wheel covers

Full wheel covers

8AE

Radios

Radio "RCD310 MP3"

7K6

Direct tire pressure monitoring system

Flat tire indicator

H2F

Tires

**Tires 205/55 R16 91H super-optimized
rolling resistance**

1G2

Spare wheel/breakdown kit

**Steel spare wheel with original
equipment tires**

3QT

Restraint systems, front

3-point seat belts with tensioner and height adjustment, front

WD4

Anti-theft alarm system "Plus"

True

4X3

Side airbag

Side air bag front with curtain air bag

2SB

Special labels/plates

Labels/plates in Polish, Estonian, Latvian, Lithuanian, Slovenian

4E2

Lock operation for tailgate/trunk lid

Tailgate/trunk lid release from inside (electrically)

3SB

Front seat, right

Standard seat, front right

3ZB

Outer rear seat belts

3-point seat belts, outer rear with ECE label

N4C

Seat trim covers

Fabric seat covering

4A0

Seat heater

Without seat heater

8Y1

Horns

PA1

Leather steering wheel (3-spoke) with decorative aluminum inserts

True

WFA

Family package, Passat station wagon, Sweden

True

6Q2

Gearshift knob/handle

Leather gearshift knob/handle

8SG

Rear combination lamps

Standard taillight assemblies (type 2)

3TB

Front seat, left

Standard seat, front left

9P1

Seat belt check

Seat belt reminder, electric contact in buckle

3C7

Center rear seat belts

3-point seat belt for center rear seat

3L3

Seat adjustment

Manual height adjustment for front seats

7L3

Start-stop system/regenerative braking

Without start/stop system without regenerative braking

QH0

Audio-response system/voice control

Two-tone horn

7Y0

Lane change assist/lane keeping system

Without lane change assistant

4B1

Protective side molding

Protective side molding

7B6

Socket

12-volt socket(s)

QN0

Drawers under front seats

Without drawers under front seats

8N3

Windshield wiper intermittent control/
light/rain sensor

**Windshield wiper intermittent control
with rain sensor**

0NB

Nameplate set

Nameplate set in base trim

1Q0

Mass damper for steering wheels

**Without mass damper for steering
wheel**

B47

Type approval countries/countries with
special requirements

Type approval the Baltic States

3CA

Partition

Without partition

3LC

Door and side trim panels

Without voice control

4KC

Side and rear windows

**Side and rear windows in heat-
insulating glass**

3Y0

Roll-up sun screen for rear and side windows

Without roll-up sun screen

2JB

Bumpers

Standard bumpers

8X0

Headlamp washer system

Without headlight washer system

3M0

Special registration measures

Without special measures

9A0

Special alarm systems

Without taxi alarm system

4K3

Door and lid locking system

**Radio remote controlled central locking
operated from inside and safe securing**

5D1

Carrier frequency for radio remote control

**Carrier frequency 433.92 MHz-434.42
Mhz**

NT0

Transit coating

Transit coating (type 1)

QV0

TV reception/digital radio reception

Door and side trim panel in foam film and woven fabric

1VG

Installation parts for engine (engine mount system)

Installation parts for four-cylinder engine

1EX

Identification plates

Special identification plate for EC for M1 passenger vehicle

1T2

First aid kit / warning triangle

Warning triangle

9F0

Preparation for sound combination for rotating beacon

Without sound combination for rotating emergency light and radio antenna preparation

9TC

Additional warning lights

Additional reflectors (door area)

7E0

Heat accumulator system/auxiliary heater

W/o heat accumulator/auxiliary heating

8FA

Second battery/battery installation

Without second battery

0TA

Floor mats

Without floor mats

3B4

Additional child seat anchors

Child seat anchor for child seat system ISOFIX

W/o TV reception/digital radio reception

1SA

Front underbody guard

Without additional front underbody guard

2A0

Delivery equipment

Without delivery equipment

9D0

Preparation for two-way radio installation

Without preparation for two-way radio installation

9W0

Telephone / telematics

W/o car phone preparation/installation

QG1

Service interval prolongation

Service interval prolongation

4GF

Windshield glass type

Windshield in heat-insulating glass

2WA

Additional tires (snow tires)

Without additional tires

4ZE

Decorative trims

Black moldings

9M0

Auxiliary heater

Without auxiliary/parking heater

UP0

Clocks

Analog clock

Vremenska crta

Pronađeno 5 zapisa

Vremenska crta zapisa za ovo vozilo

Posljednji zabilježeni podaci

2014-01

 Njemačka



Proizvedeno

Zemlja (ili država) označava lokaciju proizvodnog pogona, pogona za montažu ili registriranu adresu proizvođača. Datum može biti približan.

2014-02

 Poljska



Registrirano

Zapis predstavlja administrativni događaj. Ovo može biti povezano s promjenom vlasništva, dokumenata itd.

2017-02

 Litva



Bilo je pregledano

Zabilježen je tehnički pregled (poznat i kao MOT, tehnička inspekcija ili test kontrole emisije ispušnih plinova). Uključeni su i uspješni i neuspješni pregledi.

2017-11

 Litva



Otkriveno je oštećenje



Postoje naznake da je ovo vozilo prepoznato kao oštećeno u ovoj državi. Detalje potražite u rubrici „Oštećenja”.

2020-02



Traži se



Vozilo je proglašeno ukradenim u ovoj zemlji (ili državi). Ovo je samo podrijetlo krađe i ne pokriva sva područja koje su inače uključena u ovakvim situacijama.



+31

Izvori podataka

Provjerili smo 900+ izvora podataka u **35 država**